

CIN: L24304HP2018PLC011898

## **Gujarat Fluorochemicals Limited**

Vadodara Office: ABS Towers, 2<sup>nd</sup> Floor, Old Padra Road, Vadodara-390007, Gujarat, India Tel: +91-265-6198111/2330057

E-mail: contact@gfl.co.in, Web.: www.gfl.co.in

GFCL: BRD: 2025

The Secretary The Secretary

BSE Limited National Stock Exchange of India Limited

Phiroze Jeejeebhoy Towers Exchange Plaza, Bandra Kurla Complex

Dalal Street, Mumbai 400 001 Bandra (E), Mumbai 400 051

Scrip Code: 542812 Symbol: FLUOROCHEM

Sub: Disclosure under Regulation 30 of the SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015 - Temporary disruption of operations at

Ranjitnagar Plant, District Panchmahal, State Gujarat

Dear Sir/Madam,

We would like to inform that on 10<sup>th</sup> September, 2025, an incident occurred at the Company's Ranjitnagar Plant, where a minor rupture at one of the bellows in the gas pipeline led to a temporary gas leak. The situation was instantly brought under control through the plant's safety mechanisms. Sprinklers were activated, and the DSC control system safely halted plant operations and all personnel were immediately evacuated from the affected area.

Workers with potential gas exposures were administered immediate first-aid at our on-site Occupational Health Centre (OHC) and few of them were shifted to nearby hospitals for further treatment. We regret to report that one casualty and a few injuries have been recorded. While the post-mortem report is awaited, prima facie it appears to be during the rush of evacuation process. We deeply regret this incident and the loss of life. Our thoughts and condolences are with the bereaved family, and we are extending our full support during this difficult time.

The Company is conducting a detailed investigation and continues to prioritize the highest standards of safety across all its operations.

In terms of the Master Circular no. SEBI/HO/CFD/PoD2/CIR/P/0155 dated 11<sup>th</sup> November, 2024 issued by SEBI and pursuant to Regulation 30 read with read with sub-para 6 of Para B of Part A of Schedule III of the SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015 ("Listing Regulations"), the required details are given below:

Sr.	Particulars	Details
no.		
a)	expected quantum of loss/damage caused;	The Company has taken necessary action as an Insured and is in process of surveying and/or assessing the loss / damage caused due to the above incident.
b)	whether loss/damage covered by insurance or not including amount;	Yes, the Company has taken an Industrial All Risks Insurance (IAR) Policy. In view of this Policy, the loss of equipment, if any, and the business loss suffered on account of disruption of manufacturing operations are covered under this IAR Policy.
c)	estimated impact on the production/operations in case of strikes/lock outs etc;	There was gas leakage at Company's Ranjitnagar Plant and the Company is working towards restarting operations after due compliance of statutory requirements. However, the business





CIN: L24304HP2018PLC011898

## **Gujarat Fluorochemicals Limited**

Vadodara Office: ABS Towers, 2<sup>nd</sup> Floor, Old Padra Road, Vadodara-390007, Gujarat, India Tel: +91-265-6198111/2330057

E-mail: contact@gfl.co.in, Web.: www.gfl.co.in

		loss for disruption of production is covered under the IAR Policy of the Company.
d)	factory/unit where the	Not applicable
	strike/lock out takes place	
	including reasons for such strike.	

We request you to take the above on record.

Thanking you,

Yours faithfully, For Gujarat Fluorochemicals Limited

Bhavin Desai Company Secretary FCS 7952

